
Product data sheet Automation technology - data transmission and power supply




Product description

M12-K cable connector, Contacts: 4+PE, 8.0 - 13.0 mm, not shielded, screw clamp, IP67, M12x1.0

Area Order number M12-K series 824 99 0699 29 05



Derating curve



You can find the component part drawing and assembly instructions on the next page.

Technical data

General values

Connector design Connector locking system Termination Wire gauge (mm) Wire gauge (AWG) Cable outlet Upper limit temperature Customs tariff number Packaging Unit cable connector screw screw clamp max. 2.50 mm² max. 14 8.0 - 13.0 mm 85 °C 85369010 40

Electrical values

Rated current (40 °C) Rated voltage Rated impulse voltage UL Rated impulse voltage Pollution degree Overvoltage category Insulating material group Insulation resistance EMC compliance Degree of protection Mechanical operation

Material

Contact material Contact plating Contact body material Housing material REACH SVHC 12 A 630 V 6000 V 6000 V 3 III I > 10¹⁰ Ω not shielded IP67 > 100 Mating cycles

CuZn (brass) Au (gold) PA (UL94 V-0) PA CAS 7439-92-1 (Lead)


Product data sheet Automation technology - data transmission and power supply




Product description

M12-K cable connector, Contacts: 4+PE, 8.0 - 13.0 mm, not shielded, screw clamp, IP67, M12x1.0

Area Order number M12-K series 824 99 0699 29 05



Assembly instructions / Panel cut-out



1. Clamp out screws until bores for single wires are completely free.

2. Optional:

Change the the pre-mounted sealing ring against the alternative sealing ring when cable diameter is bigger than 10,5 mm.

- 3. Push sleeve on cable with cable clamp.
- 4. Cut off cable coating,
- 5. Strip single cores and twist single wires.
- 6. Screw single wires.
- Secure screw between contact insert and sleeve with 1 or 2 drops of Cyanoacrylate against unintentional release and screw on sleeve afterwards.
- 8. Turn on pressing screw.

Product data sheet Automation technology - data transmission and power supply



Product description

M12-K cable connector, Contacts: 4+PE, 8.0 - 13.0 mm, not shielded, screw clamp, IP67, M12x1.0

Area Order number M12-K cable connector, contacts. 447 L, 8.0 - 13.0 mm, not smelded, screw clamp, if 07, M12X M12-K series 824 99 0699 29 05

Security notices

The connector must not be connected or separated under load. Non-observance and incorrect use can result in personal injury.

The connectors are designed for use in plant, control system and electrical equipment. The end user is responsible for checking whether the connectors are suitable for use in other applications.

To prevent the connector being opened unintentionally when used in electrical circuits containing hazardous life parts, the thread between the housing and the connector head must be secured using a suitable cyanoacrylate adhesive. This does not apply to connectors used in SELV and PELV circuits according to IEC 61140 (EN 61140, VDE 0140-1).

Connectors used in electrical circuits containing hazardous life parts must only be assembled and used by or under the supervision of persons with the requisite electrotechnical training, taking the applicable regulations and standards into account.

The end user must take suitable safety measures to ensure that the connector cannot be disconnected accidentally. Connectors with degree of protection IP 67 and IP 68 are not suitable for use under water. When used outdoors, the connectors must be separately protected against corrosion. For further information about IP degrees of protection refer to 'Technical support' in the Download Centre.

To lock the cable connector to the equipment connector, the threaded ring is tightened until it is 'finger-tight' (approx. 50 cNm).