
Product data sheet Automation technology - sensors and actuators



Product description

M12-A female cable connector, Contacts: 5, 4.0 - 6.5 mm, not shielded, screw clamp, IP69K

Area Order number M12-A series 713 99 0436 684 05



You can find the assembly instructions on the next page.

Technical data

General values

Connector design Connector locking system Termination Wire gauge (mm) Wire gauge (AWG) Cable outlet Upper limit temperature Lower limit temperature Customs tariff number Packaging Unit female cable connector screw screw clamp max. 0.75 mm² max. 18 4.0 - 6.5 mm 100 °C - 40 °C 85369010 50

Electrical values

Rated current (40 °C) Rated voltage Rated impulse voltage Pollution degree Overvoltage category Insulating material group Insulation resistance EMC compliance Degree of protection

Mechanical operation

Material

Contact material Contact plating Contact body material Housing material Locking material REACH SVHC 4 A 60 V 1500 V 3 II III > $10^8 \Omega$ not shielded IP69K IP68 > 100 Mating cycles

CuZn (brass) Au (gold) PA PA stainless steel CAS 7439-92-1 (Lead)


Product data sheet Automation technology - sensors and actuators



Product description

M12-A female cable connector, Contacts: 5, 4.0 - 6.5 mm, not shielded, screw clamp, IP69K

Area Order number M12-A series 713 99 0436 684 05



Product data sheet Automation technology - sensors and actuators



Product description

M12-A female cable connector, Contacts: 5, 4.0 - 6.5 mm, not shielded, screw clamp, IP69K

Area Order number M12-A series 713 99 0436 684 05

Security notices

The connector must not be connected or separated under load. Non-observance and incorrect use can result in personal injury.

The connectors are designed for use in plant, control system and electrical equipment. The end user is responsible for checking whether the connectors are suitable for use in other applications.

To prevent the connector being opened unintentionally when used in electrical circuits containing hazardous life parts, the thread between the housing and the connector head must be secured using a suitable cyanoacrylate adhesive. This does not apply to connectors used in SELV and PELV circuits according to IEC 61140 (EN 61140, VDE 0140-1).

Connectors used in electrical circuits containing hazardous life parts must only be assembled and used by or under the supervision of persons with the requisite electrotechnical training, taking the applicable regulations and standards into account.

To lock the cable connector to the equipment connector, the threaded ring is tightened until it is 'finger-tight' (approx. 50 cNm).